



MODEL 2852-PCD Plugged Chute Detector

User Manual

Technical Support
Continental North America Toll Free 1-(800) 387-9487
Ph: +1 (905) 829-2418 Fx: +1 (905) 829-4701



A Product of Arjay Engineering Ltd. Oakville, Ontario, Canada

www.ArjayEng.com

MODEL:	
HARDWARE NO.:	5.1
SOFTWARE NO.:	
SERIAL NO.:	

2852-PCD Plugged Chute Detector



Non-intrusive monitoring of chutes and hoppers

for bulk material detection

Remote Electronics available in painted steel, SS or polycarbonate enclosure

optional alarm light

up to 1 km

and/or buzzer

Over 40 years of capacitance experience stands behind the 2852-PCD plugged chute detectors. The flush mount sensor continuously monitors the change from a normal material chute condition to a plugged condition.

- capacitance technology responds to any material type
- no moving parts
- remote alarm unit mounts safely away from pipe
- no intrusion into chute or hopper

The 2852-PCD sensor monitors the capacitance field in front of the sensor plate. The sensing plate forms part of the chute or hopper wall to sense the product within. The increased presence of product in front of the sensor due to a plugging condition increases the capacitance field and initiates an alarm.

The sensing plates are embedded into a polyethylene plate which provides monitoring without any intrusion into the product flow.

Optional Intrinsically Safe Sensor

non-intrusive monitoring of bulk product chutes and tanks

UHMWPE sensor face for erosion resistance

2852-PCD

Features and Benefits

- flush mount sensor forms part of the chute wall
- adjustable time delay and sensitivity to eliminate nuisance alarms
- remote electronics via standard twisted pair
- Sensor available Intrinsically Safe for Hazardous Locations
- high erosion resistant polyethylene resists wear
- capacitance technology responds to all types of bulk materials
- non-intrusive sensor design does not restrict product movement



Alternate probe designs are available for specialty applications.

Technical Specifications - Control Unit

Operating Temp. -20°C to +55°C
Resolution .007% (.07 pF at 1,000 pF)
Accuracy .04% of full scale pF

Power Input 12 vdc or 24 vdc or 100-240 vac +/- 10% Alarm Relay 2 x 10 amp@240 vac, SPDT, dry

Analog Output 4 mA normal/20 mA alarm
Communication Modbus RS-485

Certified UL 61010-1, 2nd Edition

CAN/CSA-22.2 61010-1-4 IEC/EN 61010-1, 2nd Edition

IEC 61326-1 CE Declared

Enclosure Type 4/IP 66 painted steel

or Type 4X/IP 66 polycarbonate or SS

Optional Light, buzzer, beacon

Technical Specifications - Sensor


Operating Temp. -60°C to +55°C
Intrinsic Safety CSA Intrinsically Safe when ordered with

to a frequency pulse for furtherance to the controller.

Approved Barrier in Control Unit Div 1, Class I, Groups A,B,C,D;

Class II, Groups E,F,G; Class III, Encl.Type 4

Wetted Parts UHMWPE (optional Teflon)







Arjay Engineering Ltd. 2851 Brighton Road Oakville, Ontario Canada L6H 6C9

TABLE OF CONTENTS

1.0	INSTRUMENT OVERVIEW				
	1.1	Features	3		
	1.2	Model Number vs. Voltage Input	3		
	1.3	Specifications	4		
2.0	INST	ALLATION	6		
	2.1	Controller Installation	6		
		2.1.1 Permanent Power Connection (AC Powered Models only)	6		
	2.2	Sensor Installation	7		
	2.3	Electrical Installation			
		2.3.1 Input / Output Terminal Specification			
	2.4	Glossary of Symbols			
3.0	STAF	RTUP AND CALIBRATION	11		
	3.1	Startup	11		
	3.2	Menu Flow Chart Background Information	11		
		3.2.1 Menu Description			
		3.2.2 Menu Flow Chart			
		3.2.3 Data Entry			
	3.3	2852 Controller Calibration			
4.0	OFT	3.3.1 Site Calibration			
4.0		JP and ALARMS			
	4.1	2852 Controller Setup			
	4.2	2852 Controller Alarms			
	4.3	2852 Controller Network			
		4.3.1 Modbus Configuration			
5.0	NAAINI	4.3.2 2800 Series Modbus Register Mapping			
6.0		ROUBLESHOOTING			
7.0	FLOV	V CHARTS	18		
		TABLE OF FIGURES			
		TABLE OF FIGURES			

Figure 1 – Electrical Installation Overview8

1.0 INSTRUMENT OVERVIEW

The Arjay Plugged Chute Detector provides a means of monitoring product within a chute, conveyor shaft, or vessel for a plugged or high product condition. The sensor is designed to mount flush within the chute wall so there is no penetration into the moving product. The sensor uses an RF Capacitance technology that does not require moving parts.

The complete 2852-PCD system consists of the flush mount sensor, the PMC card mounted at the sensor, and the 2852 controller.

Chute sensor locations can be awkward and are usually accompanied by high vibration equipment. The PMC card allows the 2852 controller to be mounted away from the sensor location for safety and ease of maintenance and set-up. The PMC card at the sensor translates the capacitance signal from the sensor into a frequency pulse, which can then be transmitted up to one kilometer to the 2852 controller via 2-wire shielded cable.

The standard sensor facing is constructed of UHMPE (ultra-high molecular weight polyethylene) for high errosion resistance and has a 304 stainless steel backing. Optional facing materials include Teflon, Nylon and PVDF.

The model is intended for use in General Purpose non-hazardous areas. For hazardous location use refer to Arjay Engineering Ltd. For appropriate model.

1.1 Features

- Microprocessor based capacitance Controller
- Relay and 4/20mA alarm output
- Modbus protocol via RS-485 for access by Arjay handheld, Central Access Panel or compatible system
- Local Auto calibration or remote calibration via network
- User specified custom features may be added by contacting Arjay Engineering Ltd.

1.2 Model Number vs. Voltage Input

- 2852-PCD-1 100-240 VAC power input
- 2852-PCD-3 12 VDC power input
- 2852-PCD-4 24 VDC power input

1.3 Specifications

Power Input: Connections to mains supply	12 VDC +15% /-10% or 24 VDC +15% /-10%, 250mA maximum 100VAC – 240VAC +/- 10%, 50/60 Hz, 150mA maximum Note: DC input models must be supplied by Limited Energy power source. Limited Energy means compliance with one of the following requirements: - Class 2 circuit according to Canadian Electrical Code, Part, I, C22 - Class 2 circuit according to National Electrical Code, NFPA-70; - Limited Power Supply (LPS) according to IEC 60950-1; - Limited-energy circuit according to IEC 61010-1.	
User Interface:	Permanent (for AC/DC model)	
Display & Keypad	Two line LCD with Alarm status display, select menu or enter values by keypad (display is internal to housing and used for set-up and diagnostics only)	
Communication Interface:	Modbus (RS485)	
Analog /Relay Outputs:		
mA Signal Output	4 mA during Normal and 20 mA during an alarm condition, 900 Ohms max OR 450 Ohms max (12VDC Power)	
Relay Output	2 SPDT relay, dry, N.O. Contact 5A @ 250 VAC (Resistive) N.C. Contact 3A @ 250VAC (Resistive), selectable failsafe non-failsafe, selectable high or low acting alarm, programma time delay: 0 – 600 seconds	
Instrument Performance:		
Measuring Range	0 - 5000 pF (most applications are 100pF to 1000pF)	
Accuracy	0.2% of setpoint	
Resolution	0.05% of setpoint via network display 0.002% of Full Scale capacitance via network display	
Calibration	Single point: Auto calibration	
Environmental:		
Operating conditions	Continuous	
Operating Temperature	-20 °C to +55 °C controller -60 °C to +55 °C PMC -60 °C to + 55 °C sensor	
Relative humidity	0 to 95% (non-condensing)	
Altitude	≤2000 m	
Installation Category	II	
Pollution Degree	2	
Equipment mobility	Fixed	

Mechanical Specification:	Refer to Dimensional Drawing		
Enclosure Rating	Type 4 / IP65 Painted Steel (Blue) Type 4x / IP66 Polycarbonate (Gray) Type 4x / IP66 316 Stainless Steel		
Options on Enclosure	Buzzer Pilot Light OR Strobe/Beacon Custom alarms		
Approval Standards:	 UL / IEC 61010-1, 2nd Edition, 2005-07-22 (Electrical Equipment for Measurement, Control, and Laboratory Use; Part 1: General Requirements) UL file number: E343390 CAN/CSA-22.2 No. 61010-1, 2nd Edition, 2004-07, (Electrical Equipment for Measurement, Control, and Laboratory Use; Part 1: General Requirements) CE: UL / IEC 61010-1; IEC / EN 61000-4; ISO 9001:2008 		

2.0 INSTALLATION

NOTE: If any damage to the instrument is found, please notify an Arjay Engineering representative as soon as possible prior to installation.

2.1 Controller Installation

Choose the mounting location in accordance with good instrument practice. Extremes of ambient temperature and vibration should be avoided (see specifications and installation drawing).

The 2850 controller may be mounted up to one kilometer from the PMC card using a minimum 18 gauge, 2-wire SHIELDED cable.

Check the polarity of the + and - wiring between the controller and the PMC prior to powering on the unit; + to + and - to - to avoid damage. Shield of cable should be connected to secondary ground terminal marked as $\frac{1}{2}$. Incoming Earth ground should be connected to primary ground terminal marked $\stackrel{\triangle}{=}$ on sub plate.

Important Note: The controller is factory set in a Failsafe mode. This means that the relays are in an energized state during normal operation. The N.O. relay contact will be held closed and the N.C. relay contact will be held open during a normal condition. This will allow the relay to return to its non-energized (shelf) state during an alarm, fault or power failure condition. Wire accordingly.

Note: Maximum Conduit size for installation size is 3/4" FNPT.

2.1.1 Permanent Power Connection (AC Powered Models only)

- 1) Connection to the building wiring system shall be in accordance with the Canadian Electrical Code (CEC), Part 1 in Canada, the National Electrical Code, ANSI/NFPA 70 in the USA, or the local electrical codes of the country where the equipment is being installed.
- 2) A disconnecting device is required. The disconnecting means shall disconnect all current-carrying conductors.
- 3) 15A circuit breaker or equivalent fuse is required.
- 4) An external switch or breaker shall be in close proximity to the equipment and within easy reach of the operator. The switch shall be marked as the disconnecting device for the equipment and include the symbols to its "ON" and "OFF" positions using the following symbols:



- 5) The wiring for AC power should be minimum 18 AWG / 300V or as required by local / country codes.
- 6) After field wiring, the primary wires must be secured to the enclosure by tie-wraps to maintain the separation from the signal wires.
- 7) Wiring diagram for permanent connection: See drawings at the back of this manual.
- 8) Use copper conductors only.

2.2 Sensor Installation

The controller is tuned to the capacitance field in front of the sensor during normal process conditions. A plugged condition will displace the air & product mix in front of the sensor with solid product. This results in an increase in the capacitance reading in picofards (pF) and will trigger the alarm relays.

Consider a mounting location where the sensor face will see a maximum product change from a normal condition to a plugged condition. Avoid locations that may incur build-up of sticky materials or do not physically change during a plugged condition.

The controller tunes itself to the capacitance reading of a normal process condition. Changes to product type or conditions such as dry vs. wet material may cause nuisance alarms and require a re-calibration.

NOTE:

To ensure proper operation and electrical safety, make sure the 2852 enclosure and the PMC junction box are electrically grounded.

If the equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.

2.3 Electrical Installation




Figure 1 – Electrical Installation Overview

TB1/TB2 - Relay Output

2 SPDT relay, Dry, N.O. Contact 5A @ 250 VAC (Resistive) and N.C. Contact 3A @ 250VAC (Resistive), selectable failsafe or non-failsafe, selectable high or low acting alarm, programmable time delay: 0 – 600 seconds

TB3 - Power Input

Power input as per Model. Check if ordered AC or DC. . Earth ground is connected to G.

TB4 - Network Output

Connect RS485 + and - to the network D+ and D-.

TB5 - 4/20 mA Output (+ and -)

The 4/20 mA is a sourced output referenced to Ground. It is not loop powered. 4mA = Normal 20mA = Alarm

TB6 - Probe Input

Connect '+' to '+', '-' to '-' between the controller and the PMC card. Check polarity to avoid damage.

TB7 – Buzzer / Red Pilot Light Output (Optional)

The connection will be factory wired if ordered.

2.3.1 Input / Output Terminal Specification

Input Terminals – Power Source					
5		HZ or DC	Specified Mains fluctuation		
TB3	<i>II</i>	100-240V	150mA	50/60Hz	± 10%
TB3	11	12 OR 24V	250mA	DC	+15% -10%

Input Terminals – Measuring Circuits					
Terminal ID	Function	Measurement Category	Nominal a.c. or d.c line to neutral voltage / if CAT I, Max. transient overvoltage Ut	Nominal a.c. or d.c current	Rating of insulation required for external circuit
TB6	Frequency	1	15V,50mA / 0		DI * or RI**
TB4	RS485 Communicati on	I	5V, 5mA / 0		DI * or RI**

^{*} Double Insulation

^{**}Reinforced Insulation

Output Terminals					
Terminal ID	Function	Isolation or protection	Rated V, A	Max. V, A	Load type and nominal
TB1	Load	Relay	N.O. Contact 5A @250VAC &		
			N.C. Contact 3A @250VAC		
TB2	Load	Relay	N.O. Contact 5A @250VAC &		
			N.C. Contact 3A @250VAC		
TB5	Current	Isolator(optional)	- 18V,20mA, 900Ω - 9V, 20mA, 450Ω	50mA@18V	
TB7	Voltage	None	24VDC, 30mA		Buzzer / Pilot Light

2.4 Glossary of Symbols



Attention, consult accompanying documents Attention, veuillez consulter les documents ci-joints.



Protective Earth
Terre de protection

Direct Current (DC)
Courant continu

Normally closed relay contacts Contacts Repos

Power on Marche (mise sous tension)

Neutral Neutre ___

Fuse

Coupe-circuit; fusible



Normally open relay contacts

Contacts travail



Power off

ArróÕ (mise hors tension)

L

Live

Sous tension

G

Ground Terre

3.0 STARTUP AND CALIBRATION

3.1 Startup

Check that the power wiring and PMC wiring are wired in accordance with the electrical installation drawing.

Power On the unit. Allow a 1 hour warm-up period before calibrating.

The Status LED on the controller circuit board should be green. A red Status LED indicates a fault condition. If red, check the Troubleshooting section.

The unit is pre-configured and tested at the factory. However, a quick field calibration is required after power up to tune the sensor to the installation conditions. See section 3.3 to calibrate the 2852-PCD.

3.2 Menu Flow Chart Background Information

The control setup, diagnostics, and calibration are accessed using the display and keypad on the controller. The Flow Chart in Section 7.0 provides an overview to the various menus and features. Keep a copy of the flow chart at hand when accessing the internal controller features.

Below is a description of the menu functions.

3.2.1 Menu Description

Since the 2852 controller has a small LCD, some menu descriptions may be in short form. The following are the menu descriptions:

Diags:DiagnosticsSENSTVTY: SensitivityCal Pts:Calibration pointsA1:Alarm relay 1Auto Cal:Auto calibrateA2:Alarm relay 2Man Cal:Manual calibrateAlarm:Alarm

Man Cal: Manual calibrate Alrm: Alarm
Cal Ok: Calibrate ok Alrm Lvl: Alarm level

Cal Err: Calibrate err Diff Hi: Differential Hi alarm set value mA out: mA output Diff Lo: Differential Lo alarm set value

mA Span: mA output span Alrm Del: Alarm Delay

Cal: Calibration point

3.2.2 Menu Flow Chart

The 2852 controller will display **Normal** in its normal operating condition and **Alarm** during a plugged chute condition.

From the main menu, you can select **Cal Only**, **View**, **and Change**.

<u>Cal Only</u> allows a user to calibrate after the equipment is installed. A calibration is required at site after initial power up or anytime a component or sensor is changed out. A password is required to enter this and is described in the calibration section.

<u>View</u> allows an operator to view the **Calibration** setpoints in pF, the **Alarms** settings such as low or high action, failsafe or non-failsafe and the 0-600 second delay, the **Diagnostics** of raw readings and the **Setup** values such as mA output and ID address. These can be viewed without a password and without risk of changing any values. This information may be requested during technical assistance inquiries.

<u>Change</u> is password protected and allows an operator to enter or change the configuration setup values indicated in the View. Changes can be made to the factory defaulted relay setpoints, delays, span etc.

3.2.3 Data Entry

Data Entry


Press $< \triangle > / < \nabla >$ key to increase / decrease the digital value.

Press <SELECT> key to move the cursor.

Press <MENU> key to abort certain screens

3.3 2852 Controller Calibration

Power up the 2852 Controller. The status LED should be green. The LCD will scroll to the normal operating screen after a series of the following screens (each displays for 2 sec.). It may read **Normal** or **Alarm** until a calibration is performed.



3.3.1 Site Calibration

A factory pre-configuration and set-up has been defaulted into the 2852-PCD. As such, a user set-up is not required in the field. A basic calibration is only required.

Be sure the sensor is wired and installed into it's final location before calibrating. The process must be operating so that the sensor face is looking at normal process conditions. For example, if solids are normally falling past the sensor, be sure this condition is occurring. This is required so that controller "Zeroes" out any background affects to the capacitance reading.

As per the Flow Chart, press and hold Menu key for 5 seconds to enter the main menu. The display will read the first menu item **Cal only**. Press select key, enter password "2000". A pF reading of the sensor will be displayed. Press select to acknowledge and then press select to accept the new calibration. To abort, press the MENU key.

If the calibration is successful, the display will return to the main operating display.

To verify the sensor and electronics are responsive, force a plugged condition, place product in front of the sensor or place your hand firmly in front of the sensor for at least 30 seconds. The high dielectric of your hand simulates a plugged condition. Verify that the control unit alarms.

The Alarm1 and Alarm2 LEDs on the circuit will activate red. Remove your hand and the alarm will clear.

If the calibration is successful, the display will return to the main operating display and show normal condition.

THIS COMPLETES THE SETUP AND CALIBRATION PROCEDURE FOR THE 2852-PCD Plugged Chute Detector

4.0 SETUP AND ALARMS

4.1 2852 Controller Setup

The 2852 controller has the following Setup parameters:

1. Sensitivity

The sensitivity determines the amount of pF change required to cause an alarm. The factory default setting is 1.0 pF. This is the most sensitive setting. Increasing the pF value will increase the amount of product required to cause an alarm. Since different products have different dielectrics, a pF to plugged chute relationship cannot be factory determined. If this setting is changed in the field, it should be tested to confirm an alarm.

2. Alarm Calibration above or below setpoint

This setting advises the controller if the calibrated pF value is above or below the alarm setpoint. For the PCD, the calibration pF value is below the setpoint because the unit is required to alarm at a higher pF value, which indicates a plugged condition. The factory default is therefore Below Setpoint.

3. Defaults

Factory settings are pre-configured into the unit based on the most typical set-up required for this application. This provides for a quick and easy calibration at site but can be changed for special applications. If the setup has been changed, this will change it back to the factory defaults.

4. Net ID

The ID number is used only for network applications. To communicate on a network, each controller must have a unique ID number. The factory default ID number is 1. Important: If multiple units on a network have the same address, network errors will result.

5. Filter

Data filtering is used to smooth data from a sudden change and minimize fluctuating readings. For example, a 5 second setting means the calculated value of the capacitance and resulting values of pF will start to respond immediately but will take 5 seconds to reach their final values. The factory default is 0 to provide an immediate and active response.

4.2 2852 Controller Alarms

The two relays on the 2852 operate together. The follow parameters are available as a common setting to the two relays:

- <u>Delay</u>. Minimum time in seconds for an alarm to exist before the relays change to an alarm state. The relay alarm state depends on the Relay Action and Failsafe settings. The factory setting is 15 seconds to suppress false alarms due to sudden of intermittent disturbances in front of the sensor.
- 2. <u>Action</u>. This determines if the Alarms LEDs should activate when the pF reading rises above or below the setpoint. The factory default is Above the setpoint because the application of a plugged chute is an increase in capacitance.
- 3. <u>Failsafe</u>. Failsafe typically means that the relay is held in an energized state when in a normal operating condition as opposed to an alarm condition. In an alarm condition, the relay de-energizes which is identical to when the instrument power is shut off. The rationale is that the alarm condition should match the Power Fail condition. The factory default is Yes for Failsafe.

4.3 2852 Controller Network

The 2852 Controller may be monitored and calibrated via RS-485 protocol compatible digital communications.

Typical features are:

1. Ease of wiring in multiple level point monitoring:

Up to 255 Model 2852's (or other Arjay 2800 Series level monitors) may be connected together in a daisy chain (2 wire communication plus power wiring) connection to an Arjay Remote Access monitor or customer control system which allows viewing data and setup of any of the transmitters on the network. The relay and analog outputs may still be used if necessary.

2. Setup for the 2852 for network operation:

Each 2852 transmitter must have a unique ID number to connect in a network system.

4.3.1 Modbus Configuration

Parameter settings: 9600 Baud Rate; Even Parity, 8 Data Bits and 1 Stop Bit.

Wiring connection: RS485 (+) connect to D+; RS485 (-) connect to D-

4.3.2 2800 Series Modbus Register Mapping

REG	Zero Based	DESCRIPTION	TYPE	No. of Reg
40001	0	Serial Number	float	2
40003	2	Hardware Rev / Software Rev	byte	1
40004	3	Sensitivity / Mode	byte	1
40005	4	Instrument Status	int	1
40006	5	Model / Modbus Address	byte	1
40007	6	Relay2 Setup / Relay 1 Setup	byte	1
40008	7	Password	int	1
40009	8	XA "A" cal parameter	float	2
40011	10	XK "K" cal parameter	float	2
40013	12	XC "C" cal parameter	float	2
40015	14	Filter	float	2
40017	16	Slope – pF per % level	float	2
40019	18	Offset – pF for empty vessel	float	2
40021	20	mA output span value	float	2
40023	22	mA output Zero value	float	2
40025	24	mA output Trim Slope value	float	2
40027	26	mA output Trim Offset vlaue	float	2
40029	28	Cal1 PV: 1st calibration point level value in %		2
40031	30	Cal2 PV: 2nd calibration point level value in %		2
40033	32	Cal1 pF: 1st calibration point capacitance value in pF		2
40035	34	Cal2 pF: 2nd calibration point capacitance value in pF	float	2
40037	36	Relay 1 : Differential High Alarm [% Level]. Only used for Linear Level type. Not used for Single Point Alarm application		2
40039	38	Relay 2: Differential High Alarm [% Level]. Only used for Linear Level type. Not used for Single Point Alarm application	float	2
40041	40	Relay 1: Differential Low Alarm [% Level] OR Single Point Alarm [pF]. Single Point Cal: used as captured pF during cal	float	2
40043	42	Relay 2: Differential Low Alarm [%Level]. Only used for Linear Level type. Not used for Single Point Alarm application	float	2
40045	44	Relay 1 On delay [in seconds]. Only used for Linear Level or Single Point Alarm application	int	1
40046	45	Relay 2 On delay [in seconds]. Only used for Linear Level type. Not used for Single Point Alarm application	int	1
40047	46	mA Analog Output	float	2
40049	48	Oscillation Frequency	float	2
40051	50	Frequency	float	2
40053	52	Capacitance	float	2
40055	54	Filtered Capacitance	float	2
40057	56	Level	float	2

5.0 MAINTENANCE

There is no routine cleaning required for this controller.

6.0 TROUBLESHOOTING

display if off 24VDC model, check the external source and polarity is correct. If the unit is a 100-240VAC model, then check the Line, Neutral and Ground wiring is correct. This indicates a major error such as memory failure, no sensor signal etc. Check the following: Make sure the PMC is installed Make sure the PMC wiring is correct and there are no breaks in the wiring. At the controller, measure across the Probe Input terminals with a DC meter. Make sure "Common" lead of meter is on "- terminal. It should read (+) 8 to (+)10 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and subject of the see 1 VDC with the PMC connected and approstic Menu (see 1 VDC with the PMC connected and see 1 VDC with the PMC connected and see 1 VDC with the see 1 VDC wi	CONDITION	DO THIS			
no sensor signal etc. Check the following: Make sure the PMC is installed Make sure the PMC wiring is correct and there are no breaks in the wiring. At the controller, measure across the Probe Input terminals with a DC meter. Make sure "Common" lead of meter is on '-' terminal. It should read (+) 8 to (+)10 VDC with the PMC connected and approximately 20 to 24 VDC with the PMC terminal disconnected. Microprocessor may have lost its parameters due to a surge in the line. Go to Diagnostic Menu (see Flow Chart) to check the Calibration values, frequency and capacitance values Call Arjay Technical Support. MPORTANT: THE UNIT SOURCES mA OUT FROM THE mA OUTPUT TERMINAL. THIS TERMINAL SHOULD NOT BE CONNECTED TO 1242V. IT IS NOT A 2 WIRE mA TRANSMITTER See Figure 4 for Electrical hookup details. Disconnect external wires from mA output and measure with mA Meter. Check the mA output Action (direct or inverse) and mA output Span are set as desired. See section 7.0 Flow chart / Change menu. If the mA output still does not match the level, then call Arjay Technical Support. 4. False Alarms Check that material is not building up on sensor Add some time delay in the unit Make sure there is no external interference and electrical noise such as motors, high voltage interference, splashing, etc Adjust the sensitivity to the next higher value. Test after any changes to confirm an alarm		Check the power to the unit. If the unit is a 12VDC or 24VDC model, check the external source and polarity is correct. If the unit is a 100-240VAC model, then check the Line, Neutral and Ground wiring is correct.			
Make sure the PMC wiring is correct and there are no breaks in the wiring. At the controller, measure across the Probe Input terminals with a DC meter. Make sure "Common" lead of meter is on '-' terminal. It should read (+) 8 to (+)10 VDC with the PMC connected and approximately 20 to 24 VDC with the PMC terminal disconnected. Microprocessor may have lost its parameters due to a surge in the line. Go to Diagnostic Menu (see Flow Chart) to check the Calibration values, frequency and capacitance values Call Arjay Technical Support. MPORTANT: THE UNIT SOURCES mA OUT FROM THE mA OUTPUT TERMINAL. THIS TERMINAL SHOULD NOT BE CONNECTED TO +24V. IT IS NOT A 2 WIRE mA TRANSMITTER See Figure 4 for Electrical hookup details. Disconnect external wires from mA output and measure with mA Meter. Check the mA output Action (direct or inverse) and mA output Span are set as desired. See section 7.0 Flow chart / Change menu. If the mA output still does not match the level, then call Arjay Technical Support. False Alarms Check that material is not building up on sensor Add some time delay in the unit Make sure there is no external interference and electrical noise such as motors, high voltage interference, splashing, etc Adjust the sensitivity to the next higher value. Test after any changes to confirm an alarm	2. If the status LED is RED	no sensor signal etc. Check the following:			
output. FROM THE mA OUTPUT TERMINAL. THIS TERMINAL SHOULD NOT BE CONNECTED TO +24V. IT IS NOT A 2 WIRE mA TRANSMITTER See Figure 4 for Electrical hookup details. Disconnect external wires from mA output and measure with mA Meter. Check the mA output Action (direct or inverse) and mA output Span are set as desired. See section 7.0 Flow chart / Change menu. If the mA output still does not match the level, then call Arjay Technical Support. False Alarms Check that material is not building up on sensor Add some time delay in the unit Make sure there is no external interference and electrical noise such as motors, high voltage interference, splashing, etc Adjust the sensitivity to the next higher value. Test after any changes to confirm an alarm		 Make sure the PMC wiring is correct and there are no breaks in the wiring. At the controller, measure across the Probe Input terminals with a DC meter. Make sure "Common" lead of meter is on '-' terminal. It should read (+) 8 to (+)10 VDC with the PMC connected and approximately 20 to 24 VDC with the PMC terminal disconnected. Microprocessor may have lost its parameters due to a surge in the line. Go to Diagnostic Menu (see Flow Chart) to check the Calibration values, frequency and capacitance values 			
measure with mA Meter. Check the mA output Action (direct or inverse) and mA output Span are set as desired. See section 7.0 Flow chart / Change menu. If the mA output still does not match the level, then call Arjay Technical Support. Check that material is not building up on sensor Add some time delay in the unit Make sure there is no external interference and electrical noise such as motors, high voltage interference, splashing, etc Adjust the sensitivity to the next higher value. Test after any changes to confirm an alarm	<u>'</u>	FROM THE MA OUTPUT TERMINAL. THIS TERMINAL SHOULD NOT BE CONNECTED TO +24V. IT IS NOT A 2 WIRE MA TRANSMITTER.			
 Add some time delay in the unit Make sure there is no external interference and electrical noise such as motors, high voltage interference, splashing, etc Adjust the sensitivity to the next higher value. Test after any changes to confirm an alarm 		 measure with mA Meter. Check the mA output Action (direct or inverse) and mA output Span are set as desired. See section 7.0 Flow chart / Change menu. If the mA output still does not match the level, 			
Make sure the product materials and moisture conditions are the same as when calibrated.	4. False Alarms	 Add some time delay in the unit Make sure there is no external interference and electrical noise such as motors, high voltage interference, splashing, etc Adjust the sensitivity to the next higher value. Test after any changes to confirm an alarm Make sure the product materials and moisture 			

ARJAY ENGINEERING TECHNICAL SUPPORT


(800) 387-9487

+1 (905) 829-2418

www.arjayeng.com

7.0 FLOW CHARTS

NORMAL OPERATING DISPLAY




Note 1: Data Entry

Press < ▲ > / < ▼ > key to increase / decrease the digital value.

Press <SELECT> key to move the cursor.

VIEW MENU




Note 1: Data Entry

Press <▲>/<▼> key to increase / decrease the digital value.

Press <SELECT> key to move the cursor.

CHANGE MENU



Note 1: Data Entry

Press < ▲ > / < ▼ > key to increase / decrease the digital value.

Press <SELECT> key to move the cursor.

Note 2: High & Low Selection

Press < ▲ > / < ▼ > key to toggle between v (low) & v (high) action.

Note 3: Yes & No Selection

Press < ▲ > / < ▼ > key to toggle between Yes & No action.